ZV 353

ORR EV x OSI EV X

# CENTRAL INTELLIGENCE AGENCY

# INFORMATION REPORT

This Document contains information affecting the National Defense of the United States, within the meaning of Title 18, Sections 793 and 794, of the U.S. Code, as amended. Its transmission or revelation of its contents or receipt by an unauthorized person is prohibited by law. The reproduction of this form is prohibited.

SECRET/CONTROL - U.S. OFFICIALS ONLY SECURITY INFORMATION 2					
COUNTRY	East Germany		REPORT	4 September 1953	
SUBJECT	1. VEB Funkanlage 2. RFT Funkwerk K	en Koepenick	NO. OF PAGES	2	
DATE OF INFO.			REQUIREMENT REFERENCES	25X1 25X1	
PLACE ACQUIRE		EVALUATED Information			
	THE SOURC	E EVALUATIONS IN THIS REPOR E APPRAISAL OF CONTENT IS T (FOR KEY SEE REVERSE)	ARE DEFINITIVE.	25X	
	EB Funkanlagen	en established within	n the present buildi	ngs <b>ef Funkwerk</b>	
Ko	pepenick. It is dire	ectly subordinate to	the Ministry of Post	s and Tele-	
8.	taken from the sta	if of Funkwerk Koepe			
ai H H	ubert Coenen ans Drechsler alter Stollberg	Head (Ex-USSR)	nick. These include	d 8	
ei H: H: W: C: E: C: O	hl taken from the sta ubert Coenen ans Drechsler	Head (Ex-USSR)	nick. These include	d s	
Hi Hi W G G O J	ubert Coenen ans Drechsler alter Stollberg erhardt Habnke Erlich, (ffu) eorg Fischer Sterreedd, (fnu) ahnke, (Fnu) and about 13 others. The new VEB is concer	Head (Rx-USSR)  Main Department Some political f  Current supply  The design work. The alighters and the build:	head unction as well as to reparations for buil	ding radio equipment,	

HAVY

(Note: Washington Distribution Indicated By "X"; Field Distribution By "井")

ARMY EST

STATE

FB!

AEC

ZOX	SECRET/CONTROL - U.S.	OFFICIALS	ONLY		25X1
-----	-----------------------	-----------	------	--	------

- 2 -

## 3. Radar (Kollisionsschutzgeraet)

The paraboloid reflector now in use can be horizontally rotated. No steps have yet been taken to make it movable in a vertical plane. The antenna has, however, been placed a short way from the focus, so that there is some vertical scattering of the beam. It is not clear if this is merely experimentaly or is to be permanent.

### 4. Manifer iron powder

The use of Manifer iron powder, produced by Hescho-Kahla, has not been very successful at Koepenick, where it is used for band filter coils in input circuits. It has been discovered that this material causes greater losses than carbonyl iron, and that it is not mechanically suited for use in fine threads.

### 5. Carbonyl iron powder

This has been received for the last six months from Gera Kondensatorenwerk, where it is pressed. Production takes place at the chemical works at Leuna. Koepenick has been receiving 50 - 100 kgs per month.

1.	Comment:	25X1
	It was later reported that the dissolution of VEB Funkanlagen was under consideration	_
	because of excessive costs and inefficiency.	1

SECRET/CONTROL - U.S. OFFICIALS ONLY